April 7, 2010 2:35:27 PM

Item ID:

D205-634-041

Accept



Setup Start

Stop



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

15/03/2010

Start Qty: 1.00 Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals: Process Plans

Required Date: 31/03/2010

Process Plan: ______QC:

Operation

Description

Date/ 3-/4-Tooling:

Date: SPC (Y/N):

_____Date:_____

Date:

Run Start

Stop ||||||||

Set Up/ Run Hours Draw Number Draw Plan Rev. Code

Accept le Qty Reject Reject Qty Number

Insp. Stamp

Work Center ID

Draw Nbr

Sequence ID/

Revision Nbr

D2580 Rev D

100

DOCUMENT CONTROL

Memo

0.00

0.00

Document Control

Photocopy D205-634 bluefile & type labels per PPP D205-634-041 CHG002

A) on CL 10/04/14

110

CNC Bend 1

BENDING MACHINE - SKIDTUBES

Memo

0.00

0.00

CNC Delta 100 Bender

1-Bend as per program D2580.C on CNC Bender and Folio FT009

2-Cut tubes as per Dwg. D2580

M

10/3/17

Dart Aerospace Ltd

									s +
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			<u> </u>						
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	\ :	_ Date: _	
	Resolution:		Disposition	າ:	_ QA: N/C Cld	sed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (NCR)			
DATE	STEP	Description of NC	Corrective Action Section			Verific	ation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
									-
									<u>.</u>

Work Order ID 56925

Page 2

April 7, 2010 2:35:27 PM

Required Date: 31/03/2010

Item ID:

D205-634-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

15/03/2010

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Process Plan: ____ Date:

QC: ____

Operation

Description

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Draw

Rev.

Plan

Code

Accept

Qty

Start Run

Reject

Qty

Stop

Reject

10/03/17

Number



Insp.

Stamp

Sequence ID/ **Work Center ID**

120

Skidtubes

Skidtubes

Memo

0.00

0.00

1- Deburr ends

QC5- Inspect part completeness to step on W/O

2- C'sink holes as per dwg without cutting fluid

3- Prepare tube for welding, remove alodine as required.

4- Scribe batch number insied aft end of tube.

130

Memo

0.00

Quality Control

Dart Aerospace Ltd

									. 4/
W/O:			WO	RK ORDER CHANG	GES	#- W- W-			
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No) :	PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQ	A:	Date: _	
Reso		solution:	Disposition	:	_ QA: N/C C	losed:		Date: _	
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (NCI	R)			
DATE	STEP	Description of NC	Corrective Action Section Initial Action Description		tion B		cation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Date		ion C	Chief Eng	QC Inspector
									-

Page 3

April 7, 2010 2:35:27 PM

Required Date: 31/03/2010

Item ID:

D205-634-041

Accept



Setup Start



Stop

Revision ID:

Item Name:

Replacement Skidtube

Start Date:

15/03/2010

QC:

Start Qty: 1.00

Reg'd Oty: 1.00



Date:

Cust Item ID: Customer:

Reference:

А	DD	ro	va	IS:

Process Plan:

Date:

Tooling:

0.00

0.00

SPC (Y/N):

Date:

Date:

Run

Start

Stop



Sequence ID/ **Work Center ID**

140

Skidtubes

Skidtubes

Operation Description

Set Up/ **Run Hours** Draw Number Draw Rev.

Plan Code

Accept Qty

Reject Reject Qty

Insp.

Number Stamp

Memo

1-Weld step D2576 as per Dwg. D2580 and QSI 004 A/R□□□ Aluminum Rod

2-Prep per QSI 005 and weld crossbolt spacers D2579 as per Dwg. D2580, QSI

For D2579 spacers, weld one side, pass 3/8" drill, weld other side, pass 3/8" drill

A/R□□□ Aluminum Rod



3-Grind welds as per Dwg D2580 Grind flush ridge made from bending

4-Drill holes for wearplates using DT 8217 & DT8937 Open holes to 19/64", adjust stopper not to hit web.Deburr

5-Counterbore crossbolt spacers to 7/16" ID x 1.0" deep as per Dwg D2580. Deburr holes

6-Drill pilot holes for aft cap using DT 8215Open holes to 0.208". Deburr

7-Drill pilot holes for Tow ring using DT8091, open to .640" and Deburr

BE 10/03/18

BE 10/03/18

BE10/03/24

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
, <u></u>			,						1 100 Wg.	
		VI								
Part No	•	PAR #:	Fault Cate	egory:	_ NCR: Y	es No	DQ.	A :	Date:	
		solution:								
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC		······································	ion B		Verific	ation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		ın & ate	Secti		Chief Eng	QC Inspector
						:				
*										

Work Order ID 56925



Page 4

April 7, 2010 2:35:27 PM

Required Date: 31/03/2010

Item ID:

D205-634-041

Accept



Setup Start



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

15/03/2010

QC: ____

Start Qty: 1.00

Reg'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: ____ Date:____

Date:

Tooling:

Run

Start

Stop

Stop



Sequence ID/

Work Center ID

150

QC

Operation Description

QC10- Inspect visual per QSI004- ground welds

Memo

Set Up/ **Run Hours**

SPC (Y/N):

0.00

Draw Number Draw Rev.

Date:

Date:

Plan Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

Quality Control

160

QC

Quality Control

QC5- Inspect part completeness to step on W/O

170

Pressure Wash per QSI005 4.3

Memo

0.00

0.00

0.00

HandFinish

Hand Finishing

Re-alodine tube as per QSI 005 section 4.1.2.1 do not acid etch and leave fwd

cap out of solution.

BR 10-4-1 D.

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _					
		esolution:											
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCF	R)							
DATE	STEP	Description of NC			on B	Verific	cation	Approval	Approval				
DAIL	SILP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	k Secti	ion C	Chief Eng	QC Inspector				
							- =						
		•											
									.				

Work Order ID 56925

March 15, 2010 8:46:54 AM



Page 5

Item ID:

D205-634-041

Accept

Setup Start



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

15/03/2010

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Process Plan: Approvals:

QC:

Date: ___

Tooling:

Date:

Date:

Run

Qty

Start

Stop

Stop



Required Date: 31/03/2010

Date:

SPC (Y/N):

Set Up/

Run Hours

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Reject Number

Insp. Stamp

Sequence ID/ Work Center ID

180

Powdercoat

Powder Coating

Operation Description

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

M118170

Memo

START TIME: OVEN TEMPERATURE:

FINISH TIME:

0.00

0.00

190

QC

Memo

QC3- Inspect Part Finish

Quality Control

0.00

Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:	*			VORK ORRED OU	ANIOEO					
W/O:			V	VORK ORDER CH	ANGES					
DATE	STEP	PR	OCEDURE C	HANGE	7,000	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-		-		
									:	
Part No	:	PAR #:	Fault Ca	tegory:	NCI	R: Yes	No DQA		Date:	
Resolution:				QA: N/C Closed: Date:						
NCR:			WORK OR	DER NON-CONFO	RMANCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action	Section B		Verifica	ation	Approval	Approval
	OIL!	Section A	Initial Chief Eng	Action Descrip	otion	Sign & Date	Sectio		Chief Eng	QC Inspector
				,						-
										
					,					

Page 6

March 15, 2010 8:46:54 AM

Item ID:

D205-634-041

Accept



Setup Start

Stop



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

15/03/2010

Start Qty: 1.00

Req'd Qty: 1.00 **Required Date:** 31/03/2010



Cust Item ID: Customer:

Reference:											
Approvals:	Process Plan:				ate:	<u>-</u>	R	tun Sta Sto			
	QC:	Date:	SPC (Y/N):	Da	ate:						
Sequence ID/ Work Center	Operation ID Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
200			0.00								

HandFinish

Hand Finishing

Memo

0.00

1-Install inserts & wearplates & Gaskets as per Dwg. D2580. Use a drop of Sikaflex on insert holes before installing wearplates,

A/R BEE Sikaflex-291 Sikaflex expire date:

2-Coat D2594-3 O' rings with Petroleum Jelly and install on D2594-1 plugs as per Dwg D2580

3-Inspect for foreign object per QSI 024

4-Install 2855 Aft Cap as per Dwg D2580 and seal Fwd Step & Aft Cap with

Sikaflex. Clean excess adhesive

A/R 🗆 🗆 Sikaflex-291. //2to Sikaflex expire date: 10/08.

5-Wing Walk as per Dwg D2580 and QSI 005 4.4

BR10-4-6, D.

Dart Aeros	pace Ltd	
------------	----------	--

W/O:			W	ORK ORDER CHANGI	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date (Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQA:	Date: _		
		esolution:	Dispositi	on:	QA: N/C Closed: Date:				
NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	Sign &	Verificat Section		Approval QC Inspector	
· · · · ·	_		Chief Eng	Chief Eng	Date				
					İ				
								:	
								ŀ	

March 15, 2010 8:46:54 AM

Required Date: 31/03/2010

Item ID:

D205-634-041

Accept



Setup Start

Stop



Revision ID:

Item Name: **Start Date:**

Replacement Skidtube

15/03/2010

Start Oty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Process Plan: **Approvals:**

Date:

Tooling:

Date:

Run Start

Stop

OC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Plan

Code

Accept

Reject Reject Qty Number

Insp. Stamp

Sequence ID/ **Work Center ID**

210

QC

Quality Control

0.00

0.00

Inspect Aft Cap, Fwd Step and Wing Walk of work to Current Step Inspect for

Foreign objects per QSI 024

QC5- Inspect part completeness to step on W/O

Draw

Rev.

Qty

220

Packaging

Packaging

Operation

Description

Memo

0.00

0.00

Packaging Identify and pack for shipping as per PPPD205-634-041

PPP Rev:

Memo

230

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

56925

Dart Aerospace	e Ltd
----------------	-------

W/O:		, , , , , , , , , , , , , , , , , , , ,	W	ORK ORDER CHANG	ES		-		
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
***			**************************************					r rod wigi	
		·					,		
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA :	.	_ Date: _	
Reso		esolution:	Dispositio	n:	_ QA: N/C Cld	sed:		Date:	<u> </u>
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCR)			. , , , , , , , , , , , , , , , , , , ,
DATE	STEP	Description of NC		on B	Verifica	tion	Approval ,	Approval	
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
					_				
				•				:	
· · · · · · · · · · · · · · · · · · ·									

March 15, 2010 8:46:59 AM

Work Order ID: 56925

D205-634-041

Parent Item Name:

Comments:

D2580-1

Parent Item:

Replacement Skidtube

IPP Rev:N□02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

Manufactured

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09

SS Wearplates & Gaskets

No

Manufactured No

110

Each

2

2

Each

2.0000

1.0000

Start Date: 15/03/2010

Start Qty: 1.00

205 Skidtube bent detail

Warehouse

Loc Oty

Loc Code

Location

Main Warehouse

LG

54541

140

128.0000 1.0000

356667 1 ND/3/17

* D2576-3 1

Step (maching detail)

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

46661 52215 128

81 47

1 I BE 10/03/18

Required Date: 31/03/2010

Required Qty: 1.00

Dart Aeros	pace Ltd
------------	----------

14//0-			3.0	10 DIV 00 DE DO 011 1110					a
W/O:			W	ORK ORDER CHANG	iES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	!					i.			
							<u> </u>		
							<u> </u>		
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Yes	s No DQ	A :	_ Date: _	77 Transplate
-	R	esolution:	Dispositi	on:	_ QA: N/C	Closed:		Date:	
NCR:		\	WORK ORE	DER NON-CONFORMA	ANCE (NC	R)			. 7
DATE	STEP	Description of NC	Initial						Approvai
		Section A	Chief Eng	Action Description Chief Eng	Sign Dat		Section C	Chief Eng	QC Inspector
									
			ļ						
									·

March 15, 2010 8:46:59 AM

Page 2

Work Order ID: 56925

Parent Item:

D205-634-041

Parent Item Name:

Replacement Skidtube

Comments:

IPP Rev:N□02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09

SS Wearplates & Gaskets JLM

Start Date: 15/03/2010

Required Date: 31/03/2010

Start Qty: 1.00

Required Qty: 1.00

D2579

Manufactured

No

140

Each

227.0000 20.0000



Crossbolt Spacer

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
LG	105		
51525	4		1
53780	. 3		
54543	18		10 1031 1 BE 84 101
56715	80		(4) DE SHE
Main Warehouse			
ST	122		
43988	4		
46434	4		
46956	2		
47797	9		
48272	2		
51314	71		
51315	30		
: B 56	6818		TO BE 10/03/18

	Dart	Aer	OS	pace	Ltd
--	------	-----	----	------	-----

	-								
W/O:			WC	RK ORDER CHANG	ES	1			
DATE STEP		PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes I	No DQA	\ :	Date:	
		solution:							
NCR:	:		WORK ORDE	R NON-CONFORMA	NCE (NCR				
DATE	STEP	Description of NC	Corrective Action Section B Verific		Verific	ation	Approval	Approval	
	JILF .	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	Section C C	Chief Eng	QC Inspector
									-
							;		

March 15, 2010 8:46:59 AM

Page 3

Work Order ID: 56925

D205-634-041

Parent Item Name:

Parent Item:

Comments:

Replacement Skidtube

IPP Rev:N \Box 02.08.28 \Box FP was QC5 in Step 27; Added QC5 to Step 30 \Box KJ IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09 SS Wearplates & Gaskets JLM

Start Date: 15/03/2010

Required Date: 31/03/2010

Start Qty: 1.00

Required Qty: 1.00

D2855

Manufactured

Purchased

No

No

200

Each

139.0000 1.0000

Cap

Warehouse	Lo	c Oty	Loc Code
Location			
Main Warehouse			
FP6		1	
56613		1	
Main Warehouse			
ST026		138	
50513		1	
50770 /		1	
51539		37	
53791		99	
	200	Each	1,397.000 2.0000

AN3-5A

Bolt

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST350	1397	
100188	188	
105057 🗸	1209	

2 fl 10-4-6.

Dart Aerospace	Ltd
----------------	-----

	-								
W/O:			W	ORK ORDER CHANG	iES				
DATE STEP		PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						·		,	
Part No		PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQ	A :	Date: _	7157
Resolution: Disposition:									
NCR:		,	WORK ORD	ER NON-CONFORMA	ANCE (NC	R)			
DATE	STEP	Description of NC	Initial		ion B		Verification Section C		Approval
			Chief Eng	Action Description Chief Eng	Date				QC Inspector
									-
	-								
		•							

March 15,*2010 8:46:59 AM

Work Order ID: 56925

Parent Item:

D205-634-041

Parent Item Name:

Comments:

AN960JD10L

Replacement Skidtube

IPP Rev:N□02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

Purchased

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09 SS Wearplates & Gaskets

No

200

Each

3,029.000 2,0000

Start Date: 15/03/2010

Start Qty: 1.00

Washer

Warehouse	Lo	c Qty	Loc Code	
Location				
Main Warehouse				
ST348		3029		
101291		16		
105793		49		
110985		2964		
	200	Each	986.0000	50.0000

ALS7-1032-130

Purchased

No

986.0000 50.0000



Insert

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST282	986	
108606	52	
111529	130	
111779	34	
112772	11	
113238	759	

50 BL10-4-6.

Page 4

Required Date: 31/03/2010

Required Oty: 1.00

Dart .	Aero	space	Ltd
--------	------	-------	-----

	•								. •
W/O:			WO	RK ORDER CHANGE	S				· ;
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						, .			
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	4 :	Date:	
		olution:							
NCR:		,	WORK ORDE	R NON-CONFORMAN	ICE (NCF	R)	. 4		g y i die alle e
DATE	STEP	Description of NC	Initial	Corrective Action Section			ation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Sign 8 Date	Section	on C	Chief Eng	QC Inspector
									-

March 15, 2010 8:46:59 AM

Work Order ID: 56925

D205-634-041

Parent Item Name:

Replacement Skidtube

Comments:

AN3C4A

Parent Item:

IPP Rev:N≘02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09

SS Wearplates & Gaskets

Purchased

No

200

Each

1,293.000 50.0000

Start Date: 15/03/2010

Start Qty: 1.00

	<u>Warehouse</u>	<u>Lo</u>
	Location	
	Main Warehouse	
	CT2.50	

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST350	1293	
112314	13	
112720	12	
112724 •	3	
112829	1	
112991	2	
113121	64	
113226	344	50 pl/0-N-6.
113644	12	
113749	11	
114103	331	
114108	500	

Page 5

Required Date: 31/03/2010

Required Oty: 1.00

Dart	Aeros	pace	Ltd

W/O:			W	ORK ORDER CHAN	GES				. Sel
DATE	STEP	PRO	OCEDURE CH		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Appr.oval QC Inspector
			-						
Part No	•	PAR #:	Fault Cate	egory:	NCR: Ye	s No [QA:	Date: _	
		solution:					,		
NCR:			WORK ORD	ER NON-CONFORM	IANCE (NO	CR)			
DATE	STEP	Description of NC			ction B	Ve	rification	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da	nox s	ection C	Chief Eng	QC Inspector
		·		·					
	1 1		1 1		l			l	ř

Picklist Prin									Page 6
	56925			·	·				
Parent Item:	D205-634-041			 					
Parent Item Name		nt Skidtube							
Comments:	IPP Rev:N	C02.08.28 GFP was QC5 in 10.02.19 per PAR09-043	vork EC	0:ПКЈ			tart Date: Start Qty:	15/03/2010 1.00	Required Date: 31/03/2010 Required Qty: 1.00
AN960C10L	14 HA HAN ANAM II XIX	Purchased	No	200	Each	388.0000	50.0000		
	NASI	149C033JR	Warehouse Location OFFSHORE FG 103585 Main Warehouse	<u>Loc (</u> 13524.		<u>Loc Code</u>		50.	BR10-4-6.
D3566-13	14 88 1 11 88 2 317 1881	Manufactured	ST 112116 112612 No <u>Warehouse</u>		288 128 160 Each	68.0000 <u>Loc Code</u>	1.0000		

<u>Warehouse</u>	Loc Qty	Loc Code	
Location			
Main Warehouse			
FP /	66		
53461	66		1 Blo4-6.
Main Warehouse			•
ST	2		
45717	1		·
50265	1		

Dart Aerospace L	Ltd
------------------	-----

W/O:			W	ORK ORDER CHAN	GES					•
DATE	STEP	PRO	OCEDURE CHA	NGE	В	y	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							-			
Part No	•	PAR #:	Fault Cate	gory:	NCR: Y	es N	lo DQA	\ :	Date:	
	R	esolution:	Dispositio	n:	QA: N/	C Clo	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	MANCE (N	ICR)				
DATE	STEP	Description of NC			ection B		Verific	ation	Approval	Approval
	0.2.	Section A	initial Chief Eng	Action Description Chief Eng		gn & Date	Section		Chief Eng	QC Inspector
					1		1			

March 15, 2010 8:46:59 AM

Page 7

Work Order ID: 56925

Parent Item:

D205-634-041

Parent Item Name:

Replacement Skidtube

Comments:

IPP Rev:N□02.08.28⊔FP was QC5 in Step 27; Added QC5 to Step 30⊔KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09 SS Wearplates & Gaskets JLM

Start Date: 15/03/2010

Required Date: 31/03/2010

Start Qty: 1.00

Required Qty: 1.00

D3566-5

Manufactured

200

Each

18.0000 1.0000



Gasket

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
FP19	15		
55026	3		20
55335	12		I SK 10-4-6.
Main Warehouse			_ ,
ST	3		
36113	1		
46186	1		
51260	1		

Dart Aerospace Ltd

								•
W/O:			WC	RK ORDER CHANG	iES		, , ,	-1
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date (Approval Chief Eng / Prod Mgr	Approval QC Inspector
<u> </u>								
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA:	Date: _	
	Re	solution:	Disposition	າ:	_ QA: N/C CI	osed:	Date: _	
NCR:	İ	,	WORK ORDI	R NON-CONFORM	ANCE (NCF	R)		
DATE	STEP	Description of NC			ion B	Verificat	ion Approval	Approval
	-	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section		QC Inspector
								-
						ļ ;		
	1 1				ı			ŀ

March 15, 2010 8:46:59 AM

Page 8

Work Order ID: 56925

Parent Item:

D205-634-041

Parent Item Name:

Replacement Skidtube

Comments:

IPP Rev:N \sqcup 02.08.28 \sqcup FP was QC5 in Step 27; Added QC5 to Step 30 \square KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09 SS Wearplates & Gaskets JLM

Start Date: 15/03/2010

Required Date: 31/03/2010

Start Qty: 1.00

Required Qty: 1.00

D3566-1

Manufactured

200

Each

25.0000 2.0000



Gasket

Warehouse	<u>L</u> c	oc Qty	Loc Code	2	
<u>Location</u>					
Main Warehouse					2 bk 10-4-6.
FP 56825	5	20			2 DK 10-4-6.
52512		3			
54480		1			
55011		1			
55320		1			
56532		14			
Main Warehouse					
ST		5			_
46349		1			
51218		1			
51259		3			
	200	Each	5.0000	1.0000	

D3564-11

Manufactured

Wearshoe

Warehouse	Loc Qty	Loc Code	
Location			. 1
Main Warehouse			1 St 10-4-6.
FP19 56834	3		- A10 10.
55332	3		
Main Warehouse			
ST	2		
45823	1		
50112	1		

Dart Aerospace Ltd

									• 🗓
W/O:			W	ORK ORDER CHANGI	ES				-,
DATE	STEP	PRO	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							:		
									f
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	_ Date: _	
		esolution:							
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NC	R)			
DATE	DATE STEP	Description of NC		Corrective Action Section B		Verific		cation Approval	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti	ion C	Chief Eng	QC Inspector
								1	-
				·					

Pic	kl	ict	Pri	nt

Mârch 15, 2010 8:46:59 AM

Page 9

Work Order ID: 56925

Parent Item:

D205-634-041

Parent Item Name:

Replacement Skidtube

Comments:

IPP Rev:N□02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

Manufactured

IPP Rev. O 06.02.28 Added paperwork EC

SS Wearplates & Gaskets IPP Rev:P 07-07-09

Start Date: 15/03/2010

Required Date: 31/03/2010

Start Qty: 1.00

Required Qty: 1.00

D3564-13

Manufactured

No

200

Each

29.0000 1.0000

Wearshoe	

Warehouse	Loc	: Oty	Loc Code		
<u>Location</u>					
Main Warehouse					
FP17 /		17			
56285		17			1 DK 10-4-6
Main Warehouse					1 75% 10
ST		12			
45409		2			
46495		10			
No	200	Each	14.0000	1.0000	

Wearshoe

D3564-9

Warehouse Location	Loc Qty	Loc Code
Main Warehouse		
FP19	12	
55334	12	
Main Warehouse		
ST	2	
44659	1	
45825	1	

1 pl 10-4-6_

Dart Aerospace L	Ltd
------------------	-----

-								•
		WC	ORK ORDER CHANG	GES				
STEP	PROCEDURE CHANGE By					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	
Re	solution:	Disposition	n:	QA: N/C C	osed:		Date:	
							*******	1
STEP	Description of NC	Description of NC Corrective Action			Verific	cation Approval	Approval	
0.2.	Section A	Initial Chief Eng	Action Description Chief Eng				Chief Eng	QC Inspector
								-
	•						÷	
						-		
		:PAR #: Resolution:	STEP PROCEDURE CHARACTER STEP PAR #: Fault Cate Resolution: Disposition WORK ORDI STEP Description of NC Section A Initial	STEP PROCEDURE CHANGE PAR #: Fault Category: Resolution: Disposition: WORK ORDER NON-CONFORM STEP Description of NC Section A Secti	PAR #: Fault Category: NCR: Yes Resolution: Disposition: QA: N/C CI WORK ORDER NON-CONFORMANCE (NCF STEP Description of NC Section A Section B Initial Action Description Sign 8	STEP PROCEDURE CHANGE By Date PAR #: Fault Category: NCR: Yes No DQ. Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Chief Eng/Prod Mgr :PAR #: Fault Category: NCR: Yes No DQA: Date:

Mårch 15, 2010 8:46:59 AM

Page 10

Work Order ID: 56925

D205-634-041

Parent Item Name:

Replacement Skidtube

Comments:

Parent Item:

IPP Rev:N□02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

Manufactured

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09 SS Wearplates & Gaskets JLM

Start Date: 15/03/2010

Start Qty: 1.00

Required Date: 31/03/2010

Required Qty: 1.00

D3564-5

Manufactured

200

Each

28.0000

1.0000

Wearshoe

Warehouse	Lo	e Qty	Loc Code	
Location				
OFFSHORE				
FG		2		
34806		2		
Main Warehouse				
FP19		25		_
51925		1		
55024 ✔		12		1 / pk 13-4-6.
55333		12		
Main Warehouse				
ST		1		
45824		1		
	200	Each	420.0000 16.0000	

D2594-3

O-Ring, 205 Skidtube

Warehouse	Loc Qty	Loc Code
Location		-
Main Warehouse		
FP /	407	
51613 55546	27	
55546 🗸	380	
Main Warehouse		
ST	13	
52562	13	

16. A-10-4-6.

Dail ACIUSDACE LIC	rt Aerospace	Ltd
--------------------	--------------	-----

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							ļ		
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Dispositi	on:	_ QA: N/C (Closed:		Date:	
NCR:		V	VORK ORI	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti		Chief Eng	QC Inspector
		·							· -

March 15, 2010 8:46:59 AM

Page 11

Work Order ID: 56925

Parent Item:

D205-634-041

Parent Item Name:

Replacement Skidtube

Comments:

IPP Rev:N□02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09 SS Wearplates & Gaskets JLM

Start Date: 15/03/2010

Required Date: 31/03/2010

Start Qty: 1.00

Required Qty: 1.00

D2594-1

Manufactured

No

200

Each

513.0000 16.0000



Plug, 205 Skidtube

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
FP	385		
54008	1		
54643	15		
55002✔	369	16 DK 10-4-1	
Main Warehouse		70.71.70 16.	
ST	128	· .	
42221	16		
42807	92		
43884	3		
46435	2		
51527	9		
51757	6		



	DESIG	**	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
	CHEC	KED	APPROVED	DRAWING NO. REV. D
		THE STATE OF THE S		D2580 SHEET 1 OF 3
	DATE			TITLE SCALE
	07.0	02.27		205 SKIDTUBE ASSEMBLY NTS
_	Α		96.09.16	NEW ISSUE
	В		96.12.02	AS MANUFACTURED
	C		98.08.26	REDRAWN, INCLUDED DEO 9094/9097
	D		07.02.27	CHANGE TO SS WEARPLATES AND

GASKETS, INCLUDE DEO 9124/9183



QTY -041	QTY -045	Part Number	Description	
X	-045	D2580-041	SKIDTUBE ASSEMBLY	
	X	D2580-045	SKIDTUBE ASSEMBLY	
_	 ^- -	D2300-043	SKIDTOBE ASSEMBLT	
1	1	D2500-1-190	EXTRUSION	
1	1	D2576-3	STEP	
20	24	D2579	CROSS BOLT SPACER	
16	16	D2594-1	PLUG	
16	16	D2594-3	O-RING	
1	1	D2596	205 WEB	
1	1	D2855	AFT CAP	
1	1	D3564-5	WEARSHOE	
1	1	D3564-9	WEARSHOE	
1	1	D3564-11	WEARSHOE	
1	1	D3564-13	WEARSHOE	
2	2	D3566-1	GASKET	
1	1	D3566-5	GASKET	
11	1	D3566-13	GASKET	
50 50 ALS7-1032-130			INSERT	
		or AKS7-1032-130		
		or AKS4-1032-130		
		or AELS-1032-130		
50	50 50 AN3C4A		BOLT	
2	2	AN3-5A	BOLT	
50	50	AN960C10L	WASHER	
2	2	AN960JD10L	WASHER	

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED OF
SUBJECT TO AMENING NOTHER WORK OKOLAR
NO. SUBJECT STORMS OF SUBJECT STORMS OF SUBJECT

GENERAL NOTES:

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 2) ALL DIMENSIONS ARE IN INCHES
- 3) INSERT D2596 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241 ADHESIVE PER DART QSI 015 BEFORE BENDING. ENSURE HOLES LINE-UP.
- 4) BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM CENTERLINE RADIUS OF 60 AND ENDING WITH A MINIMUM RADIUS OF 30. A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE.
- 5) USE DART DRILL TEMPLATE TD2577-205 TO LOCATE AND DRILL Ø0.297 HOLES FOR WEARSHOE INSERTS. INSTALL ALS7-1032-130 PER SECTION D-D (50 PLACES) AFTER FINISH. INSTALL AN3C4A BOLTS AND AN960C10L WASHERS WITH SIKAFLEX-241/-291.
- 6) WELDING TO BE DONE PER DART QSI 004.
- 7) FINISH:


SEE NOTES ON PAGE 2 FOR D2580-041 AND


PAGE 3 FOR D2580-045

8) INSERT D2594-1 PLUG C/W D2594-3 O-RING IN HOLES MARKED 'P' (BOTH SIDES OF TUBE) AFTER FINISH (16 PLACES).

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.





NO. 227

AWS D17.1.2001 QUALIFICATION TEST RECORD

Name: Bardag Elliett	
Job number: 569250	
Part number: <u>D205-634-041</u>	
Description: 205 skid tube	
Welding Process: Tig[/ Mig[]	
Base materiel: Aluminum	
Current: AC[] DC[]	

TEST REQUIREMENTS AND RESULTS

Visual:	pass[fail[]
Penetration:	pass[1]	
<u>UNACCEPTABLE</u>		
Cracks:	pass[/]	fail[]
Undercut:	pass[v]	
Pin holes:	pass[]	fail[]
Overlap (cold lap)	pass[]	fail[]
Porosity (surface):	pass[1]	fail[]
Coloration:	pass[/]	fail[]
i		
Qualifier Lad Same	_Date of Te	st Coupon <u>v 03.19</u>
Welder Booker Sturt	Date of Te	est Coupon <u>/ (- (3 - / 9</u>
		•

The above named individual is qualified in accordance with AWS D17.1.2001 to weld